

PUBLIC RECORD SUMMARY — NOT AN OFFICIAL REPORT

This document recreates the Colorado DR3447 Investigator's Traffic Crash Report format using publicly available crash data. It is not a legal document. To obtain the official report, contact the investigating agency. PII fields are redacted per CRS 24-72-204.

Data Coverage: 33% 39/120 fields

COLORADO CRASH REPORT SUMMARY

DR3447 Format — Public Record Data — Generated by CrashStory

PAGE A — CRASH SCENE INFORMATION

Page 1

CASE NUMBER P23-30860		CRASH ID 386077		AGENCY ORI DGOPD		AGENCY NAME Colorado Department of Transportati...		FORM VERSION DR3447	
DATE OF CRASH 09/05/2023		TIME OF CRASH 04:22		OFFICER ARRIVED —		SCENE CLEARED —		CRASH SEVERITY O — N/A	
CDOT REGION —		TPR (All), Southwest		DISTRICT —		DATA SOURCE TABLEAU		RECORD STATUS NEW	
NUMBER KILLED 0		NUMBER INJURED 0		TOTAL VEHICLES 1		NON-MOTORISTS 0		INJURY K 0	INJURY A 0
								INJURY B 0	INJURY C 0
Secondary Crash Construction Zone School Zone Alcohol Drug Marijuana Speed Related Hit & Run ■ Juveniles									

CRASH LOCATION

LATITUDE 37.27603		LONGITUDE -107.87682		COUNTY La Plata (20)		CITY/TOWN DURANGO		URBAN/RURAL —	
ON ROAD / STREET E 3RD AVE				INTERSECTING / REFERENCE ROAD E 12TH ST			MILEPOINT —		HIGHWAY # 0350
ROADWAY TYPE City Street		SPEED LIMIT (MPH) 10		TRAFFIC CONTROL —		LOCATION Intersection Related		LANE POSITION —	
ROAD SECTION 3RDAV									

HARMFUL EVENT SEQUENCE

1ST HARMFUL EVENT 47 — Electrical/Utility Box		2ND HARMFUL EVENT —		3RD HARMFUL EVENT —		4TH HARMFUL EVENT —	
MOST HARMFUL EVENT 47 — Overhead Structure				TOP TRAFFIC OFFENSE —			

ROAD CHARACTERISTICS

ROAD CONTOUR (CURVES) Straight		ROAD CONTOUR (GRADE) Level		ROAD DESCRIPTION Railroad		APPROACH/OVERTAKING —	
SYSTEM CODE 7		RR CROSSING —		CRASH TYPE GROUP Collision with Object		COMMON CODE —	

ENVIRONMENTAL CONDITIONS

LIGHTING Daylight		ROAD CONDITION Dry		WEATHER (PRIMARY) Clear		WEATHER (SECONDARY) —	
----------------------	--	-----------------------	--	----------------------------	--	--------------------------	--

PAGE B — NARRATIVE

Electrical/Utility Box

VEHICLE / OCCUPANT INFORMATION

Case: P23-30860 — 09/05/2023 — E 3RD AVE

PAGE C — MOTORIZED TRAFFIC UNITS

TRAFFIC UNIT #1

VEHICLE TYPE Station Wagon	YEAR —	MAKE —	MODEL —	COLOR —	BODY TYPE —	SPECIAL FUNCTION Taxi				
VEHICLE CONDITION No Defects		DAMAGE DESCRIPTION —		TOWED No		TRAILERS —				
DRIVER NAME REDACTED — PII		DRIVER ADDRESS REDACTED — PII		DRIVER AGE 42	DRIVER GEND... —	DRIVER LICENSE # REDACTED — PII				
DIRECTION OF TRAVEL North		VEHICLE MOVEMENT Going Straight		SPEED LIMIT (MPH) 10	EST. SPEED (MPH) —	STATED SPEED —				
DRIVER ACTION Other Contributing Action		DRIVER ACTION 2 —		HUMAN CONTRIBUTING FACTOR No Contributing Factor		AUTONOMOUS LEVEL —				
CONTRIBUTING FACTOR 1 No Contributing Factor		CONTRIBUTING FACTOR 2 —		CONTRIBUTING FACTOR 3 —						
SAFETY EQUIP AVAILABLE Shoulder and Lap Belt		SAFETY EQUIP USED Properly Used		SAFETY EQUIP DETAIL Shoulder and Lap Belt - Properly Used						
Alcohol Suspected Marijuana Suspected Other Drugs Suspected DUI Hit & Run Emergency Lights										
#	SEAT POS	AGE	SEX	INJURY	EJECT	AIRBAG	RESTRAINT	HELMET	SAFETY EQ	IMPAIRMENT
1	Sleeper Section	10	—	No Apparent Injury (O)	No	Not Deployed	Properly Used	N/A - Cars/Tr...	Shoulder and Lap ...	—